	CLASSIFICATIONSECRET	
COUNTRY	East Germany REPORT NO.	
TOPIC	Briesen Airfield	
	i i	
EVALUATION	PLACE OBTAINED	25X1 25X1
DATE OF CONTE		25 X 1
DATE OBTAINED	26 October 1355	25X1
REFERENCES		
PAGES	3 ENCLOSURES (No. & TYPE)	
	LNOLOGONES (NO. & III 2)	25X1
REMARKS	<u> </u>	
generalisis rejectivi militari et 100 dilimbir de dilimbir de 100 dilimbir de	This is UNEVALUATED Information	
graphyn Addiniolaid i La Ynd an Gridnesdau dai ddin ddin		
:		25 X 1
	· · ·	, f
	*	i
1.	The following air activity and aircraft were observed at Briesen airfield between 21 September and 3 October 1955:	
	21 September. Between 0800 and 1600, there was air activity by IL-28s and UIL-28s with auxiliary fuel tanks. The weather was favorable. A total of 41 IL-28s and/or UIL-28s were parked on the dispersal area along the southern taxiway.	25X1
	22 September. After 1100, IL-28s and UIL-28s	25X1
	took off, temporarily flew in regimental formation, then dispersed, flew individually and, after a flight time of about 45 minutes, landed at the field.	
	24 September. At 1150, 26 IL-28s crossed over the field, flying from east to west. The aircraft turned west of the field, and	
	then headed east toward the field. They flew in 8 wedge formations of 3 followed by 2 individual aircraft. Shortly	
	before approaching the field, all aircraft lowered their landing gears and descended to about 1,000 meters. When flying east of	
	the field, the aircraft again turned, while dispersing formation. Heading west, the aircraft crossed over the field, keeping a	
	distance of about 1,000 meters between one another. It could not be observed if the aircraft again assembled in formations west	
	of the field. The aircraft did not land at the field but they retracted their landing gears after the individual flights coross	
	the field.	25X1
	. At 1610, one Li-2 landed at the field. At 1800, 47 jet bombers and 1 Li-2 were parked on the dispersal areas, along the southern taxiway.	25 X 1
	28 September. Between 2300 and 0100, when the moon was shining bright 10 flights were made by IL-28s, which remained aloft for about 20 minutes.	htly,
	FLASH	25X1
	CLASSIFICATION SECRET	

Sec. har		
		25X1
- 2 -		
	5	
•		
2) September. At 1000, 18 jet bombers flying in 6 formations aft of each other headed west. The distant between the aircraft was about 1,000 meters. There we 7/10 overcast at an altitude of 4,000 meters. The aircturned to the field at 1200 and landed within examinutes.	nce Vas a ircraít	25 X 1
		25X1
30 September. After 0800, when the weather was favoured by the bombers individually took off at intervals of 2 headed west. Some of the aircraft were fitted with a fuel tanks. It could not be observed if the aircraft in formation. At 1400, the aircraft returned from the landed within 19 minutes. At 2200, in clear moonshin bombers took off at intervals of 15 to 20 minutes. Expending aloft for about 25 minutes.	minutes and uxiliary assembled as west and us. ld ie	
1 October. After 0800, individual IL-28s and UIL-28 at intervals of 15 minutes and headed west. The sky partially overcast. Each aircraft remained aloft for minutes. The total number of aircraft involved in aircould not be observed. Air activity was discontinued Afterwards, 51 jet bombers were observed on the field 44 along the southern taxiway and 7 in the revetment the field. Throughout the day, the air force soldier field did not dring any alcohol, because a general hat the field.	was 30 to 35 r activity at 1400. d, including s around	
2 October. During the morning, individual flights we by jet bombers, one of which had an accident. This a which approached from the east for landing, flew at sof 2,000 meters with extended landing gear approxima meters east of the field. Although this aircraft approximated to land, it did not descend, but suddenly divertically down to 100 or 150 meters. Then it pulled about 800 meters, and suddenly pitched down, breaking which whirled through the air and came down near the station. The engines were apparently running at high aircraft crashed onto the southern taxiway. The landstorn off in the crash and thick smoke developed. Howe	ircraft, an altitude tely 1,000 arently ed almost up te g its rudder, flight control speed, as the ing rear was	
aircraft did not catch fire. The listorted rudder lay at least 500 meters from titself. From a distance no major damages could be rec	the aircraft	25X1 25X1
the plane, except for the missing rudder and landing accident at 1150, air acticity was immediately discount	gear.	25 X 1 25 X 1
-column as 11)0, all accretty was immediately discor	ncinged.	

Approved For Release 2008/01/23 : CIA-RDP80-00810A008400050010-6

SECRET

SECRET	OEV4
	25X1
- 3 -	
and the second of the second o	
At 1800, a total of 51 jet bombers were observed on the airfield. The damaged plane and 29 aircraft were seen along the southern taxiway and 21 in the revetments.	
3 October. At 1100, when the weather was almost cloudless, 18 IL-28s took off to the east, within 4 minutes and 45 seconds. The aircraft assembled in 6 wedge formations of 3 and headed north. Approximately over the Koenigswusterhausen area, the formation turned to the west and disappeared in this direction. The formation returned at 1500. All 18 aircraft landed within 7 minutes.	
After 30 September, more aircraft were stationed at the field than previously. The arrival of the additional aircraft could not be observed, except for the 4 planes which had landed on 24 September.	
	25X1
Comment. The two IL-28 units stationed at Briesen airfield participated in exercises held by the Third Shock Army in the Letzling Heath area. In connection with these sorties, bombs were dropped over the training field. The increased aircraft strength indicates that aircraft of another regiment, presumably from Werneuchen, were temporarily stationed at the field. The intermediate landing fields used during the cross-country flights	25X1
on 30 September and 3 October 1955 have not been determined.	25X1 25X1

Secret .

25X1